



FIG.2A




FIG.2B




FIG.3A




FIG.3B




FIG.4



FIG.5A




FIG.5B




FIG.6




FIG.7




FIG.8




FIG.9




FIG.10




FIG.11




FIG.12A




FIG.12B




FIG.12C




FIG.13




FIG.14A




FIG.14B




FIG.14C




FIG.14D




FIG.15




FIG.16




FIG.17




FIG.18A













FIG.19

| COMBINATION | MARKS                                                                               | OUTPUT OF SENSORS                                                                    |
|-------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| 1           |    |    |
| 2           |  |  |
| 3           |  |  |
| 4           |  |  |