






FIGURE 1B

Technical drawing of a mechanical assembly in cross-section. The drawing shows a large circular component (1) with a central cavity (2). A smaller component (3) is located inside the cavity. A needle-like component (20) is shown inserted into the assembly, with a small circular feature (21) near its tip. Other components are labeled 4, 5, 10, 12, 40, and 41. The drawing includes hatching for cross-sections and dimension lines.

FIGURE 2A






FIGURE 3A

5




FIGURE 3B