

PLATING METHOD

ABSTRACT

Copper electroplating baths having a surface tension of ≤ 40 mN/m are suitable for filling vias with copper, where such copper deposits are substantially void-free and substantially free of surface defects.

Figure 2A