ABSTRACT

A method for indicating a transmit power includes: determining a maximum permissible transmit power of at least one uplink beam of a terminal, in which the maximum permissible transmit power is a maximum transmit power subject to satisfying a maximum permissible exposure (MPE) limit of the terminal; and transmitting first indication information for indicating the maximum permissible transmit power of the at least one uplink beam.

Figure 2