




FIG. 1




FIG. 2A




FIG. 2B







FIG. 2C

Energy cost from melting (J/cm^3)

Intrinsic stretchability (%)

Intrinsic conductivity (S/m)

PU: Polyurethane; PDMS: Polydimethylsiloxane; SEBS: Styrene-ethylene-butylene-styrene; PVA: Poly Vinyl Alcohol

FIG. 2D




FIG. 3A




FIG. 3B




FIG. 3C




FIG. 3D




FIG. 3E




FIG. 4A




FIG. 4B



FIG. 4C




FIG. 4D




FIG. 4E




FIG. 4F




FIG. 4G




FIG. 4H




FIG. 4I




FIG. 4J

10/28




FIG. 4K



FIG. 5A




FIG. 5B




FIG. 5C




FIG. 5D




FIG. 5E




FIG. 5F




FIG. 6A




FIG. 6B




FIG. 6C




FIG. 6D




FIG. 6E



FIG. 6F




FIG. 6G




FIG. 7A




FIG. 7B




FIG. 7C




FIG. 7D




FIG. 7E




FIG. 8A




FIG. 8B




FIG. 8C




FIG. 8D




FIG. 8E




FIG. 8F




FIG. 8G




FIG. 9A




FIG. 9B




FIG. 9C




FIG. 9D




FIG. 9E




FIG. 9F




FIG. 9G




FIG. 9H




FIG. 9I




FIG. 9J




FIG. 9K




FIG. 9L




FIG. 9M




FIG. 9N




FIG. 90




FIG. 9P