

ABSTRACT - Figures 1 to 12

A method for abandoning a branch main 1 joined to a fluid-carrying spine main 2 comprises gaining access to the bore of the branch main 1 at an access point and then permanently blocking the bore of the branch main 1 at a blockage point closer to the junction than to the access point.

THIS SHEET HAS BEEN
REPLACED

This Sheet Has Been Replaced

