



F I G. 1



F I G. 2



F I G. 3

	301	302	303	304	305	306
No	File Name	Long Text	Direction	Input Name	Priority	Rotation
1	Base BMP Partition 45.bmp	PARTITION 45mm	0	0	0	0
2	Base BMP Mark None.bmp	MARKING WITH CROSS ARROW	1	1	1	0
3	Base BMP EL.bmp	ELECTRICITY	2	1	0	1
4	Base BMP Mark.bmp	L-SHAPE	2	0	0	0
	⋮					

F I G. 4 A

501

51 INPUT OF SHAPE

END OF DRAWING EDITING

52 PLEASE SELECT SHAPE AND PRESS "NEXT".

53

PREVIEW

54

SHAPE LIST

No	SHAPE NAME
1	PARTITION 45mm
2	CROSS ARROW
3	ELECTRICITY
4	L-SHAPE

55

56

SELECT DIRECTION

57 BACK

58 DECISION

502

51 INPUT OF DETAILS OF SHAPE

END OF DRAWING EDITING

52 PLEASE SELECT DIRECTION AND PRESS "NEXT".

59

DIRECTION

TOP

BOTTOM

LEFT

RIGHT

57 BACK

60 DECISION

F I G. 4 B






FIG. 4C



F I G. 5





FIG. 6



F I G. 7




FIG. 8




FIG. 9

901

SELECTION OF MARKING POINT

PLEASE SELECT MARKING POINT FROM LIST.

DISPLAY OF MAP

FILTER :

FILTER CONDITION SETTINGS **AMONG ELECTRIC EQUIPMENT FILTERS** 91

No	NAME	X COORDINATE	Y COORDINATE	SHAPE	SITUATION
	ELECTRICITY 1	100	100	ELECTRICITY	UNDONE
	ELECTRICITY 2	50	150	ELECTRICITY	UNDONE
	ELECTRICITY 3	150	50	ELECTRICITY	UNDONE
	ELECTRICITY 4	50	50	ELECTRICITY	UNDONE

92