

12 SEP 2002



163163



G00002




FIG. 1




FIG. 2

3/7




FIG. 3

4/7




FIG. 4A

5/7

Second Failure - Line 3




FIG. 4B

Second Failure - Module 3




FIG. 4C

7/7




FIG. 5