




Figure 1




Figure 1




Figure 2




Figure 4




Figure 3




Figure 5

Tobacco Material Extraction




Figure 6

Loss of moisture due to flash vaporisation

Inlet moistness 50%




Figure 7




Figure 8




Figure 9