Figure 1A




Figure 1B




Figure 1C




Figure 1D





Figure 1E






Figure 1F




Figure 1G




Figure 1H




Figure 1I




Figure 1J




Figure 1K




Figure 1L




Figure 2




Figure 3



M-1
Saw
Die Attach
D/A Cure
Wire Bond
Molding
Laser Mark
Singulation
Packing
Shipping
100
200
300
400
500
600
700
800
900

Figure 4



M-2
Pre-Plated L/F
Molding
Saw
Die Attach
D/A Cure
Wire Bond
Window Seal
Laser Mark
Singulation
Packing
Shipping
101
102
103
202
303
404
505
606
707
808
909

Figure 5