

1/21




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5

6/21




FIG. 6




FIG. 7

8/21




FIG. 8

9/21




FIG. 9




FIG. 10




FIG. 11

12/21




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17

INGOT 1




FIG. 18




FIG. 19




FIG. 20




FIG. 21