

ABSTRACT**METHOD FOR INK JET FAULT COMPENSATION
USING EXTRA INK DOTS**

A printing method identifies where parts of an image will not be printed due to device failure and if possible prints extra ink dots in adjacent columns so as to lessen the visual effect of failure to print correctly at the original location.

Figure 3