

Drawings

Insert Rewrite	Function 1 	Function 2 	Function 3 	Function 4 	Function 5 	Function 6 	Function 7 	Function 8 	Function 9 	Function 10 	Function 11 	Function 12
Delete	Symbol Exit	Symbol Table	Symbol Pause	Symbol Symbol	Symbol Symbol	Symbol Symbol	·7 Symbol	·8 Symbol	·9 Symbol	/ Symbol	Function Combination	
Start-Of- Line	Symbol 	Symbol 	Symbol 	Symbol 	Symbol 	Symbol 	·4 	·5 	·6 	* 	Backspace ←	
End-Of-Line	Symbol 	Symbol 	Symbol 	Symbol 	Symbol 	Symbol 	·0 	·1 	·2 	·3 	Enter ↵	
Page up	Symbol 	Symbol 	Symbol 	Symbol 	Symbol 	Symbol 	+ 	- 	. 	= 	Symbol ↑	
Down Page Turning	Screenshot	Control	Select	Shift	Space			Shift	Wind ow	Num Lock Switch ←	Caps Lock Switch →	Screen Lock
					Left Key		Right Key					
							Control Cursor		Three Key Indicators			

Fig. 1

Insert	F1 	F2 	F3 	F4 	F5 	F6 	F7 	F8 	F9 	F10 	F11 	F12
Delete	Esc	Tab	Pause Break	!	°	:	·7 .	·8 ,	·9 ;	/ ?	Fn	
Home	} [	)]	] 2	> 3	 4	\ 5	·4 6	·5 7	·6 8	* 9	Back Space ←	
End	_ 0	— 1	~ 2	... 3	, 4	· 5	·0 6	·1 7	·2 8	·3 9	Enter ↵	
Page Up	@ 0	# 1	& 2	% 3	°C 4	\$ 5	+ 6	- 7	. 8	= 9	No. ↑	
Page Down	Print Screen /SysRq	Ctrl	Alt	Shift	Space			Shift		NumL ←	CapL →	ScroL ↓
					Left Key		Right Key					
							Control Cursor		Three Key Indicators			

Fig. 2

Drawings

Insert	F1 	F2 	F3 	F4 	F5 	F6 	F7 	F8 	F9 	F10 	F11 	F12 
Delete	Esc	Tab	Pause Break	!	<	≠	'	"	...	?	Fn	
Home	} Q	) W	 E	> R	 T	\ Y	4 U	5 I	6 O	* P	Back Space ←	
End	_ A	— S	~ D	≈ F	, G	· H	0 J	1 K	2 L	3 ;	Enter ↵	
Page Up	@ Z	# X	& C	% V	°C B	\$ N	+ M	- ,	. .	= /	No. ↑	
Page Down	Print Screen /SysRq	Ctrl	Alt	Shift	Space			Shift		NumL ←	CapL →	ScroL ↓
					Left Key 		Right Key 		Control Cursor 		Three Key Indicators 	

Fig. 3

Screen shot	Pause	↑	Symbol Delete 7 7 7	Symbol Backspace 8 8 8	Symbol 9 9 9	Symbol /
←	→	↓	Symbol 4 4 4	Symbol 5 5 5	Symbol 6 6 6	Symbol Insert / Rewrite *(Space)
Number Switch	Caps Lock Switch	Screen Lock	Symbol Start-Of-Line 0 0 0	Symbol End-Of-Line 1 1 1	Symbol 2 2 2	Symbol 3 3 3
UP Page Turning	Down Page Turning	Symbol Shift Enter	Symbol Control +	Symbol Select -	Symbol Window .	Symbol Function Combination =
Left Key		Right Key	Control Cursor Three Key Indicators			

Fig. 4

Control Cursor		Left Key	Right Key
Three Key Indicators			
Symbol Delete 7 7 7	Symbol Backspace 8 8 8	Symbol ↑ 9 9 9	Symbol /
Symbol ← 4 4 4	Symbol → 5 5 5	Symbol ↓ 6 6 6	Symbol Insert / Rewrite *(Space)
Symbol Start-Of-Line 0 0 0	Symbol End-Of-Line 1 1 1	Symbol Page up 2 2 2	Symbol Page Down 3 3 3
Symbol Shift Enter	Symbol Control +	Symbol Select -	Symbol Window .
Symbol Function Combination =			

Fig. 5

Drawings

Print Screen / SysRq	Pause Break	↑	> Delete 7 7 7	] BackS 8 8 8	) 9 9 9	# Tab /
←	→	↓	, 4 4 4	; 5 5 5	: 6 6 6	@ Insert * (Space)
Num Lock	Caps Lock	Scroll Lock	& Home 0 0 0	! End 1 1 1	? 2 2 2	° PgUp PgDn 3 3 3
Page Up	Page Down	Shift Enter	Ctrl +	Alt -	Win .	Fn = Esc
Left Key		Right Key	Control Cursor	Three Key Indicators		

Fig. 6

Control Cursor		Left Key	Right Key
Three Key Indicators			
> Delete 7 7 7	] BackS 8 8 8	) 9 9 9	# Tab /
, 4 4 4	; 5 5 5	: 6 6 6	@ Insert * (Space)
& Home 0 0 0	! End 1 1 1	? PgUp 2 2 2	° PgDn 3 3 3
Shift Enter	Ctrl +	Alt -	Win . Fn =

Fig. 7

Print Screen / SysRq	Pause Break	↑	> Delete 7 sx	] BackS 8 tuz	) 9 vwy	# Tab /
←	→	↓	, 4 klm	; 5 nop	: 6 qr	@ Insert * (Space)
Num Lock	Caps Lock	Scroll Lock	& Home 0 ab	! End 1 cd	? 2 efg	° PgUp PgDn 3 hij
Page Up	Page Down	Shift Enter	Ctrl +	Alt -	Win .	Fn = Esc
Left Key		Right Key	Control Cursor	Three Key Indicators		

Fig. 8

Control Cursor		Left Key	Right Key
Three Key Indicators			
> Delete 7 sx	] BackS 8 tuz	) 9 vwy	# Tab /
, 4 klm	; 5 nop	: 6 qr	@ Insert * (Space)
& Home 0 ab	! End 1 cd	? PgUp 2 efg	° PgDn 3 hij
Shift Enter	Ctrl +	Alt -	Win . Fn =

Fig. 9

□	○	□	/
○	□	○	*
○	□	○	□

Fig. 10

Drawings



Fig. 11



Fig. 12-1



Fig. 12-2



Fig. 12-3



Fig. 12-4



Fig. 13



Fig. 14



Fig. 15