

ABSTRACT

For the purpose of providing both a component-manufacturing tool, which can be chucked to a chuck table even under a heated environment, and a component-manufacturing method, a component-manufacturing tool 1 includes a frame body 10 and a holding film 20 covering an opening 10h, in which: a frame body 20 includes a first frame 11 and a second frame 12; the holding film 20 includes a base layer 21 and a holding layer 22 provided on one surface of the base layer 21, and the holding film 20 is sandwiched and held between the first frame 11 and the second frame 12 in a stretched state; and a ratio R_{E1} ($= E'(100)/E'(25)$) of an elastic modulus $E'(100^{\circ}\text{C})$ of the base layer 21 to an elastic modulus $E'(25^{\circ}\text{C})$ of the base layer 21 is $0.2 \leq R_{E1} \leq 1$, and $E'(25)$ is 35 MPa or more and 3500 MPa or less. The present component-manufacturing method includes: a component holding step of holding components to the holding layer 22 of the component-manufacturing tool 1; and a chucking step of chucking and fixing the holding film, to which the components are held, to a surface of a heated chuck table.

[FIG. 1]