



1/21

FIG. 1A**FIG. 1B**

2/21

FIG. 1C





FIG. 2



4/21

FIG. 3









FIG. 4



6/21

FIG. 5**FIG. 6A**

7/21

FIG. 6B**FIG. 6C**

8/21



FIG. 6D

FIG. 7



10/21

FIG. 8




FIG. 9




FIG. 10




FIG. 11






FIG. 12 (Continued)

Etched cubes




105 ± 5 nm
81%

Oversized cubes
and low purity





133 ± 6 nm
63%

Not cubes





FAILED

15/21

FIG. 13**FIG. 14**

16/21

FIG. 15**FIG. 16**

17/21



FIG. 17**FIG. 18**

FIG. 19






FIG. 20



20/21

FIG. 21



21/21

FIG. 22

