

1/4

FIG. 1






FIG. 2




2/4

FIG. 3



3/4

FIG. 4



4/4

FIG. 5





FIG. 6

Elongation without heating



Elongation after heating immediately

