

Arsenic profile
18
17
Arsenic (Units)
pad ox thickness
= 100A
pad ox thickness
= 50A
-0.060 -.040 -.020 0 0.020 .040 .060 .080 0.100
Y(Microns)
Arsenic profile in channel

FIG. 4



Si
Ox
Shallow
implantation
Vt implant
Sacrificial implantation illustration

FIG. 5



Arsenic profile
18
17
Arsenic (Units)
pad ox thickness
= 100A
pad ox thickness
= 50A
-0.060 -.040 -020 0 0.020 .040 .060 .080 0.100
Y(Microns)
Arsenic profile in channel

FIG. 4



Si
Ox
Shallow
implantation
Vt implant
Sacrificial implantation illustration

FIG. 5