

Smart Mirror
100




FIG. 1




FIG. 2A




FIG. 2B




FIG. 2C





FIG. 3A






FIG. 3C




FIG. 3D

SQUARE HOLE ON RIGHT
BEND IN CORRECT DIRECTION




FIG. 4A




FIG. 4B




FIG. 4C





FIG. 4D



HOLE CALLOUTS:

- HOLE A: 8 PLACES, 8-32 EXTRUDED AND TAPPED
- HOLE B: 8 PLACES, CS FOR 8-32 FLAT HEAD SCREW
- HOLE C: 8 PLACES, CS FOR 4-40 FLAT HEAD SCREW
- HOLE D: 4 PLACES, HOLE FOR M6 PEM NUT, 0.34" DIA
- HOLE E: 4 PLACES, HOLE FOR PEM SO-440-20, 0.17" DIA
- HOLE F: 10 PLACES, HOLE FOR PEM SO-440-12, 0.17" DIA
- HOLE G: 9 PLACES, HOLE FOR PEM FH-832-6X STUD, 0.16" DIA
- ⑥ HOLE H: 2 PLACES, CS FOR M3 SCREW

FIG. 4E




FIG. 5A




FIG. 5C

FIG. 5B




FIG. 5D





FIG. 5E



HOLE A: 4 PLACES, 0.26" DIA
HOLE B: 8 PLACES, CS FOR 8-32 FLAT HEAD SCREW, ON OUTSIDE SURFACE
HOLE C: 2 PLACES, 0.18" DIA

FIG. 5F




FIG. 6A




FIG. 6B




FIG. 6C



FIG. 6D





FIG. 7A



FLAT PATTERN

FIG. 7B



FIG. 7C

FIG. 7D




FIG. 8A




FIG. 8B




FIG. 8C




FIG. 8D




FIG. 9A




FIG. 9B




FIG. 9C






FIG. 9D




GLASS DIMENSIONS

FIG. 10A



SAFETY FILM
WITH PRINTING

FIG. 10B



SAFETY FILM
PLACEMENT

ALIGN SAFETY FILM
TO BOTTOM EDGE OF GLASS

FIG. 10C

AREA SHOWN IN DARK GRAY
SHALL BE BLACK.

AREAS SHOWN IN LIGHT GRAY
SHALL BE TRANSPARENT.




FIG. 10D




FIG. 11A




FIG. 11B




FIG. 11C



FIG. 11D




FIG. 11E

30000043 TOP BAR




FIG. 11F




FIG. 12A




FIG. 12B




FIG. 12C




FIG. 12D





FIG. 12E



HOLE A: 4 PLACES, 8-32 EXTRUDED AND TAPPED HOLES
HOLE B: 4 PLACES, HOLE FOR M6 PEM NUT

FIG. 12F




FIG. 13A




FIG. 13B





FIG. 14A






FIG. 15A




FIG. 15C

FIG. 15B




FIG. 16A




FIG. 16B





FIG. 16C



HOLE A: 2 PLACES, 8-32 EXTRUDED AND TAPPED

FIG. 16D




FIG. 16E




FIG. 17A




FIG. 17B

FLAT PATTERN

FIG. 17C




FIG. 17D

FIG. 17E




FIG. 18




FIG. 19




FIG. 20

2100




FIG. 21




FIG. 22




FIG. 23A




FIG. 23B




FIG. 24A

In Workout Connectivity Break - Heal Flow




FIG. 24B




FIG. 24C




FIG. 25




FIG. 26A




FIG. 26B




FIG. 26C




FIG. 27




FIG. 28A




FIG. 28B



FIG. 28C



FIG. 28D



FIG. 28E



FIG. 28F




FIG. 29A



FIG. 29B




FIG. 29C



FIG. 30A



FIG. 30B



FIG. 30C




FIG. 31A




FIG. 31B




FIG. 31C




FIG. 31D




FIG. 31E




FIG. 31F




FIG. 31G




FIG. 31H




FIG. 31I




FIG. 31J




FIG. 31K



FIG. 31L




FIG. 31M




FIG. 32A



FIG. 32B



FIG. 32C




FIG. 33A




FIG. 33B




FIG. 33C