

FIG. 1

1/16




FIG. 2

2/16




FIG. 3

3/16




FIG. 4

4/16




FIG. 5

5/16




FIG. 6

6/16




FIG. 7

7/16




FIG. 8

8/16




FIG. 9

9/16





FIG. 10

10/16

Rapid Discharge Forming of PdNiCuP & Vitreloy 1 BMG rods






FIG. 11a

FIG. 11b

12/16




FIG. 11c

13/16




FIG. 11d

14/16




FIG. 11e

15/16




FIG. 12a

16/16




FIG. 12b

