
FIG. 1


1. Electrolytic degreasing
2. Cleaning with pure water
3. Pickling (a 10% sulfuric acid, 30 seconds)
4. Cleaning with pure water
5. Nickel plating treatment
6. Cleaning with pure water
7. Palladium plating treatment
8. Cleaning with pure water
9. Gold plating treatment
10. Cleaning with pure water
11. Drying