




FIG. 1




FIG. 2




FIG. 3


Combination	Arrangement of marking	Outputs of sensors
1		21 OFF 21 OFF
2		21 OFF 21 ON OFF
3		21 ON OFF 21 OFF
4		21 ON OFF 21 ON OFF

FIG.4




FIG. 5




FIG. 6




FIG. 7




FIG.8




FIG. 9




FIG.10




FIG.11

3c




FIG.12




FIG. 13




FIG. 14