




Fig. 1A





Fig. 1B








Fig. 2B




Fig. 3A




Fig. 3B





Fig. 3C

450
↓**Fig. 4**




Fig. 5

9/14

$$OV = k_1(EP) + k_2(IP) + k_3(T) + k_4(TC)$$

k_1 = weighting constant

k_2 = weighting constant

k_3 = weighting constant

k_4 = weighting constant

OV = output value

EP = exterior photosensor output

IP = interior photosensor output

T = temperature sensor output

TC = tint command output

Fig. 6

	k_1	k_2	k_3	k_4
schedule 1	0.13	0	0	0
schedule 2	0.10	0.35	0.22	0.52
schedule 3	0.15	0.35	0.11	-0.52

Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11




Fig. 12