METHODS OF REMOVING EXTRANEOUS AMOUNTS OF MOLDING MATERIAL FROM A SUBSTRATE

Abstract of the Disclosure

Methods for removing thin layers of extraneous multi-component molding material from one or more areas on a substrate. The methods include exposing the substrate to a plasma effective to remove a non-particulate component of the molding material from each area. The methods further include exposing the substrate to a non-plasma process effective to remove a particulate component of the molding material from the area.

FIG. 1

162162

G00002