



FIG. 1

(a)



(b)

CASE WHERE GAP BETWEEN STEEL
PIPE SHEET PILES AND STEEL SHEET
PILE IS NARROWER THAN PLANNED



(c)

CASE WHERE GAP BETWEEN STEEL
PIPE SHEET PILES AND STEEL SHEET
PILE IS WIDER THAN PLANNED




FIG. 2






FIG. 3


(a)



(b)



(c)



(d)






FIG. 4

(a)



(b)



(c)





FIG. 5

(a)



(b)




FIG. 6




FIG. 7




FIG. 8





FIG. 9

(a)



(b)




FIG. 10





FIG. 11




FIG. 12




FIG.13




FIG.14

