

A Method of Applying Polysilazane Coating onto the surface of Copper Wire or Strips for Electrical Insulation

Drawings




FIG 1



FIG 2




FIG 3