1/4




Fig. 1



33
35
37
34
36
31
38
30
39
(a)
Grip
Shearing angle
31
39
(b)
32
α
31
40
Pulling
Motor Drives
(c)

Fig. 2



53
42
(a)
43
44
42
51
Compression force helps to iron the mask onto the plate surface.
43
49
42
(b)
42
49
49
49
44
49
53
48
55
47
55
42
44
48
(c)

Fig. 3



1. Clamping & Peeling
Push to peel position.
Pull to stack position.
9
53
43
45
(a)
2. Peeling & Compress
Full compression
Stacking position.
58
45
(b)
3. Compress & Detach pull
Detach pull
45
(c)
4. Stacking completed
Return to initial
33
45
(d)

Fig. 4





Fig 1






Fig 2

REPLACEMENT SHEETS
05 JANUARY 2006




53
42
(a)
44
43
42
51
Compression force helps to iron the mask onto the plate surface.
43
49
42
42
(b)
48
49
49
49
44
49
53
55
47

Fig 3


55
44
42
48
(c)




Fig 4

REPLACEMENT SHEETS
05 JANUARY 2006