




Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9





Fig. 10

**Fig. 11**




Fig. 12




Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18




Fig. 19

$N_{HP}=0, N_{LP}=100$




Fig. 20a

$N_{HP}=50, N_{LP}=50$




Fig. 20b




Fig. 21a




Fig. 21b




Fig. 22a

Fig. 22b




Fig. 23




Fig. 24





Fig. 25






Fig. 27





Fig. 28




Fig. 29





Fig. 30

**Fig. 31**




Fig. 32




Fig. 33




Fig. 34






Fig. 35








Fig. 38a




Fig. 38b

	T1	T2	T3	T4	T5	T6	T7	T8	T9	T10	T11	T12
U1	0	0	0	0	$C_{1,5}$	$C_{1,6}$	$C_{1,7}$	$C_{1,8}$	$C_{1,9}$	$C_{1,10}$	0	0
U2	0	0	0	0	$C_{2,5}$	$C_{2,6}$	$C_{2,7}$	0	0	0	0	0
U3	0	0	0	0	0	0	0	0	$C_{3,9}$	$C_{3,10}$	$C_{3,11}$	$C_{3,12}$
U4	0	0	0	0	0	0	$C_{4,7}$	$C_{4,8}$	$C_{4,9}$	$C_{4,10}$	0	0
U5	0	$C_{5,2}$	$C_{5,3}$	0	$C_{5,5}$	$C_{5,6}$	0	0	0	0	0	0
U6	0	0	0	$C_{6,4}$	0	0	0	$C_{6,8}$	$C_{6,9}$	0	0	$C_{6,12}$
U7	$C_{7,1}$	$C_{7,2}$	0	$C_{7,4}$	$C_{7,5}$	0	0	0	0	0	0	0
U8	$C_{8,1}$	$C_{8,2}$	$C_{8,3}$	$C_{8,4}$	0	0	0	0	0	0	0	0

Fig. 39

	T1	T2	T3	T4	T5	T6	T7	T8	T9	T10	T11	T12
U1	0	0	0	0	$C_{1,5}$	$C_{1,6}$	$C_{1,7}$	$C_{1,8}$	$C_{1,9}$	$C_{1,10}$	0	0
U2	0	0	0	0	$C_{2,5}$	$C_{2,6}$	$C_{2,7}$	0	0	0	0	0
U3	0	0	0	0	0	0	0	0	$C_{3,9}$	$C_{3,10}$	$C_{3,11}$	$C_{3,12}$
U4	0	0	0	0	0	0	$C_{4,7}$	$C_{4,8}$	$C_{4,9}$	$C_{4,10}$	0	0
U5	0	$C_{5,2}$	$C_{5,3}$	0	$C_{5,5}$	$C_{5,6}$	0	0	0	0	0	0
U6	0	0	0	$C_{6,4}$	0	0	0	$C_{6,8}$	$C_{6,9}$	0	0	$C_{6,12}$
U7	$C_{7,1}$	$C_{7,2}$	0	$C_{7,4}$	$C_{7,5}$	0	0	0	0	0	0	0
U8	$C_{8,1}$	$C_{8,2}$	$C_{8,3}$	$C_{8,4}$	0	0	0	0	0	0	0	0

Fig. 40

	T1	T2	T3	T4	T5	T6	T7	T8	T9	T10	T11	T12
U1	0	0	0	0	$C_{1,5}$	$C_{1,6}$	$C_{1,7}$	$C_{1,8}$	$C_{1,9}$	$C_{1,10}$	0	0
U2	0	0	0	0	$C_{2,5}$	$C_{2,6}$	$C_{2,7}$	0	0	0	0	0
U3	0	0	0	0	0	0	0	0	$C_{3,9}$	$C_{3,10}$	$C_{3,11}$	$C_{3,12}$
U4	0	0	0	0	0	0	$C_{4,7}$	$C_{4,8}$	$C_{4,9}$	$C_{4,10}$	0	0
U5	0	$C_{5,2}$	$C_{5,3}$	0	$C_{5,5}$	$C_{5,6}$	0	0	0	0	0	0
U6	0	0	0	$C_{6,4}$	0	0	0	$C_{6,8}$	$C_{6,9}$	0	0	$C_{6,12}$
U7	$C_{7,1}$	$C_{7,2}$	0	$C_{7,4}$	$C_{7,5}$	0	0	0	0	0	0	0
U8	$C_{8,1}$	$C_{8,2}$	$C_{8,3}$	$C_{8,4}$	0	0	0	0	0	0	0	0

Fig. 41




Fig. 42




Fig. 43




Fig. 44




Fig. 45




Fig. 46




Fig. 47




Fig. 48




Fig. 49




Fig. 50




Fig. 51




Fig. 52