

[Figure 1]

Treatment Flow

(after Etching of Cu Layer)

Immersion in Basic Potassium Permanganate Solution having Composition: A



Immersion in Neutralizer: B



Washing with Water (arbitrarily) → Drying (arbitrarily)

[Figure 2]

