SUSPENSION, HEAD SUSPENSION ASSEMBLY, AND DISK DRIVE APPARATUS

ABSTRACT

Provision of holes (3c) in the ribs (3b) of a head suspension assembly (3) can decrease the displacement of a head slider (2), that is caused by Karman vortex streets which occur near the ribs (3b) in association with the rotation of the magnetic disk (1).

FIG.3.