






FIG. 1



25xLE











FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24





FIG. 25



625

OPERATING MAIN CYCLE




FIG. 27

MOSQUITO TRAP: 021—312

CONTROL PANEL 310 ↗

CURRENT STATUS:
TIME: 11:33 —314
STATE:
FILLING PUMP: OFF —314
PURGING PUMP: ON —316
WATER LEVEL:
SATELLITE BREEDING CONTAINER 320 ↗

#1: H
#2: H
#3: *L*
#4: H
#5: H
#6: H

FILLING CONTAINER:
PURGING CONTAINER:

EMAIL LOG:

REPORT NAME	TIME STAMP
0010	01:00
0011	02:00
0012	03:00

REPORT OPTION SELECTION:
EMAIL ADDRESS: [maintenance@trap.com]

REPORT MODE SELECTION —322
TALKING: N
DIAGNOSITC: Y
SUPERVISOR: N

FIG. 28

330 ↗


REPORT NAME: 0011

WATER LEVEL

TIME STAMP	BREEDING CONTAINER #1 (cm)	BREEDING CONTAINER #2 (cm)	BREEDING CONTAINER #3 (cm)	BREEDING CONTAINER #4 (cm)	FILLING CONTAINER (cm)	PURGING CONTAINER (cm)
01:30	L	L	L	L	L	L
01:35	H	H	H	H	H	H
01:40	H	H	H	H	H	H

TIME STAMP	FILLING PUMP	PURGING PUMP
1:30	ON	ON
01:35	ON	OFF
01:40	ON	OFF

FIG. 29



35




FIG. 31




FIG. 32




FIG. 33




FIG. 34




FIG. 35




FIG. 36




FIG. 37




FIG. 38




FIG. 39

534
↙

PURGING			
1	ON	THU	1800H
2	OFF	THU	1815H
3	ON	THU	2100H
4	OFF	THU	2115H
5	ON	FRI	0300H
6	OFF	FRI	0315H
7	ON	SUN	1800H
8	OFF	SUN	1815H
9	ON	SUN	2100H
10	OFF	SUN	2115H
11	ON	MON	0300H
12	OFF	MON	0315H

536
538

FIG. 40




FIG. 41




FIG. 42




FIG. 43




FIG. 44




FIG. 45




FIG. 46




FIG. 47




FIG. 48




FIG. 49




FIG. 50




FIG. 51




FIG. 52




FIG. 53




FIG. 54




FIG. 55




FIG. 56




FIG. 57




FIG. 58




FIG. 59




FIG. 60