

Abstract**Planarity Alignment of Stencils and Workpieces**

An alignment system for a workpiece printing machine comprises a stencil support and a
5 workpiece support, and a planarity control mechanism having at least two actuators
arranged to effect relative rotation of the stencil support and workpiece support about both
the horizontal axes.

FIG. 2