

FIG. 1




FIG. 2



Process	Decal transfer onto membrane via substrate	Direct spray coating on membrane
Steps involved	(a) Coating of electrocatalyst on a flexible substrate (b) Lamination of a substrate to the membrane (c) Peeling of the substrate from membrane 	(a) Layer by layer spraying of catalyst (b) Multiple spray nozzles 

FIG. 3




FIG. 4A




FIG. 4B




FIG. 5




FIG. 6

