

FIG. 1








FIG 2



Creaming and phase separation



Heavy sediment due to insoluble minerals such as calcium

2/6




FIG. 3




FIG. 4A



FIG. 4B




FIG. 4C




FIG. 5




FIG. 6

