


FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6



placing the cleaned substrate onto the carrier member
S10
transferring the carrier member together with the substrate into a drying chamber to perform drying treatment
S20

FIG. 7