

14
37
L
37
26
38
55
24
57
203
34
35
44
11
18
45
54
56
36
28
10
28
36

FIG. 1A



W
26
24
203
44/45
11
18
203
36
28
10
28
36

FIG. 1B




FIG. 1C




FIG. 2A



W
16
16
16
15
15
15
11
10
28
28

FIG. 2B



202
202
W
16
16
16
15
15
15
11
18
203
203
10
30
28
28
30

FIG. 2C




FIG. 2D




FIG. 3A




FIG. 3B



37
L
37
26
38
55
24
57
34
35
44
45
54
203
56
11
18
36
28
10
28
36

FIG. 3C



DEPOSIT PAD OXIDE
DEPOSIT HARD MASK
PATTERN HARD MASK
ETCH TO FORM ISOLATION TRENCH
IMPLANT TILTED NON-DOPANT ATOMS
FILL ISOLATION TRENCH
CMP
REMOVE HARD MASK

FIG. 4



W
16
16
16
15
15
15
11
10
29
28
28
29

FIG. 5A



202
W
16
16
16
15
15
15
11
18
204
204
204
204
203
203
203
203
10
29
28
28
29

FIG. 5B



36
W
36
204
204
203
203
11
204
204
203
203
10
28
28
29

FIG. 5C



DEPOSIT PAD OXIDE
DEPOSIT HARD MASK
PATTERN HARD MASK
ETCH TO FORM ISOLATION TRENCH
FILL ISOLATION TRENCH WITH BLOCKING MATERIAL
ETCH BLOCKING MATERIAL TO FILL ISOLATION TRENCH PARTLY
IMPLANT TILTED NON-DOPANT
FILL ISOLATION TRENCH
CMP
REMOVE HARD MASK

FIG. 6



202
19
17
16
16
15
15
12
13
203
10
28

FIG. 7



DEPOSIT PAD OXIDE
DEPOSIT FIRST HARD MASK
PATTERN HARD MASK
ETCH TO FORM ISOLATION TRENCH
DEPOSIT ETCH STOP LAYER FOR SECOND HARD MASK
DEPOSIT SECOND HARD MASK
PATTERN SECOND HARD MASK AND ETCH STOP LAYER
IMPLANT TILTED NON-DOPANT
FILL ISOLATION TRENCH
CMP
REMOVE ALL HARD MASK AND PLANARIZE

FIG. 8