

1/8




FIG. 1A




FIG. 1B

x x x x x		x x x				
	x x x x x		x x x			
x x x x x		x x x x x x x x x		x x x		
	x x x x x		x x x x x x x x x	x x x		
		x x x x x	x x x x x	x x x x x x x x x	x x x	
				x x x x x	x x x x	x x x
x x x x x					x x x x x	x x x x x x x

FIG. 2

2/8

300




FIG. 3A

3/8




FIG. 3B

4/8






FIG. 3C



6/8

X		X				
	X		X			
X		X		X		
	X		X	X		
X	X	X	X	X	X	
				X	X	X
X					X	X

FIG. 4A

X		X				
	X		X			
X		X		X		
	X		X	X		
X	X	X	X	X	X	
				X	X	X
X		Y		Y	X	X

FIG. 4B

1	3	2	4	1	3	5	2	4	5	1	2	3	4	5	6	5	6	7	1	3	5	6	7
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

1	3	5	8	11	17	20	25
---	---	---	---	----	----	----	----

FIG. 5

1	4	7	10	13	16	19	22
---	---	---	----	----	----	----	----

FIG. 6

8/8




FIG. 7




FIG. 8