

1/5




Figure 1
PRIOR ART




Figure 2

2/5




Figure 3

3/5






Figure 4

4/5




Cross section after first cut

Fig. 5(a)



Cross section after multiple cuts along the same dicing line

Fig. 5(b)



First layer removed after first cycle
Second layer removed after second cycle
Third layer removed after third cycle
...
Last layer removed after n^{th} cycle

Cross section of the dicing lane

Fig. 5(c)

5/5




Figure 6




Figure 7