

Sensing measurement initiator
Sensing measurement responder
Third request frame
1201
Third response frame
1202

FIG. 12



Sensing measurement initiator
Sensing measurement responder
Control frame, where the control frame may include indication information, and the indication information may indicate, to the sensing responder, that a sensing measurement session corresponding to at least one AP in a MAP sensing measurement session identified by a MAP measurement session ID field is to be terminated
1501
1502
Parse the control frame

FIG. 15



Control frame
Termination (Termination)
Number of terminated APs (number of terminated AP)
MAP sensing initiator AP MAC address (MAP Sensing Initiator AP MAC Address)
MAP measurement session ID indication (MAP Measurement Session ID Indication)
MAP sensing responder AP MAC address (MAP Sensing Responder AP MAC Address)
Bits: 1
n*8
48
8
n*48

FIG. 16