




FIG. 1

2/17




FIG. 2





FIG. 3


4/17

400




PASSING 402


416



BRIGHT ROX 404




ROX SPOTTING 406




ROX STRIPPING 408

414



SPOT POINT BRIDGE 410



REFORMATting ERROR 412

FIG. 4

5/17




FIG. 5




FIG. 6




FIG. 7

8/17




FIG. 8




FIG. 9




FIG. 10

1100

PREDICTED

PASSING	BRIGHT ROX	ROX SPOTTING	ROX STRIPPING	STOP POINT BRIDGING	REFORMATTING
1166	0	53	0	19	1
1	5	7	0	1	1
51	0	878	1	6	3
2	0	19	23	0	0
16	0	14	0	161	0
0	0	6	0	0	71

PASSING

BRIGHT
ROX

ANNOTATED

ROX
SPOTTING

ROX
STRIPPING

STOP POINT
BRIDGING

REFORMATTING

FIG. 11

12/17




FIG. 12




FIG. 13




FIG. 14




FIG. 15

16/17





FIG. 16

**FIG. 17**