

ABSTRACT

A zero-voltage soft switching (ZVS soft switching) control method and a power control circuit using the same are provided. The ZVS shot switching control method includes the following
5 steps. A trapezoidal current control is executed to shape an inductor current into a plurality of trapezoidal waveforms.

FIG. 1