

**MANUFACTURING METHOD OF GLASS STRIP, GLASS STRIP, AND GLASS
SUBSTRATE**

ABSTRACT

A method of manufacturing a glass strip includes heating and drawing including heating and softening a glass plate preform in a heating furnace, and drawing the softened glass plate preform with a desired thickness. The drawing includes maintaining a positive pressure in the heating furnace with respect to an atmospheric pressure, and drawing the softened glass plate preform in such a manner that gas flows become identical on both surfaces of the glass plate preform in the heating furnace.

Figure 3