





FIG. 1




2/4

FIG. 2**FIG. 3**

3 / 4

FIG. 4

4 / 4

FIG. 5

MIXING RATIO PARTIAL DISCHARGE
CHARACTERISTICS (KRAFT PAPER)