




FIG. 1A




FIG. 1B




FIG. 2











FIG 4A, Run A, $Z^*=6.0$ FIG 4B, Run B, $Z^*=6.0$ FIG 5A, Run A, $Z^*=6.0$ 


Parameter	Estimate
a	0.04258
L	47.2808
b	2.05055

FIG 5B, Run B, $Z^*=6.0$ 





Parameter	Estimate
a	0.0439
L	44.6409
b	2.14807

FIG. 4C, Run C, $Z^*=8.0$ FIG. 4D, Run D, $Z^*=8.0$ FIG. 5C, Run C, $Z^*=8.0$ 

Parameter	Estimate
a	0.03294
L	27.0685
b	2.15387






FIG. 5D, Run D, $Z^*=8.0$ 

Parameter	Estimate
a	0.03203
L	20.3132
b	2.16695



Parameter	Estimate
a	0.02614
L	9.15832
b	2.31399

Parameter	Estimate
a	0.02104
L	0
b	2.3177

FIG 6A, Run A, $Z^*=6.0$ FIG 6B, Run B, $Z^*=6.0$ FIG. 6C, Run C, $Z^*=8.0$ FIG. 6D, Run D, $Z^*=8.0$ FIG. 6E, Run E, $Z^*=10.5$ FIG. 6F, Run F, $Z^*=10.5$ 