

FIG. 1




FIG. 2




FIG. 3

TBL

	IDm	LOCATION INFORMATION
Rb1	X00001	A01234
Rb2	X00002	A01234
Rb3	X00003	5B
⋮	⋮	⋮

FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14

TBLK		INF _x		
	IDt	INF1	INF2	T
Rc1	A01234	LONG. 136° 15' E., 35° 45' N.	AZUSA NO. 2	13:00
Rc2	A01235	TOKAIDO LINE, 2KM FROM SHINAGAWA, TO YOKOHAMA	AN ACCIDENT AT TOTSUKA	9:50
⋮	⋮	⋮	⋮	⋮

FIG. 15

