

FIG.1




FIG.2





FIG.3

FIG.4





FIG.5

FIG.6

Factory	Apparatus	Operated State	Operating State	State Time
Factory X	Apparatus A	Online/Remote	Reset	00:05:00
	Apparatus B	Online/Remote	Idle	—
	Apparatus C	Online/Remote	Processing	—
Factory Y	Apparatus D	Online/Local	MA	00:30:00
	Apparatus E	Online/Remote	Idle	—
	Apparatus F	Online/Remote	Down	00:15:00
Factory Z	Apparatus G	Online/Remote	Processing	—
	Apparatus H	Online/Remote	Reset	00:10:00
	Apparatus I	Online/Remote	MA	00:20:00

FIG.7




FIG.8




FIG.9




FIG.10

1001

Detailed Information Regarding Error
Error Code: 101
Error Factor: Measurement Error
Detailed Description of Error

Display Procedure

Display Data

FIG.11

1101
└

Procedure Information
Procedure 1
Procedure 2
Procedure 3
Procedure 4
Procedure 5
Procedure 6
Procedure 7
Procedure 8
Procedure 9
Procedure 10

FIG.12