

C
R
A
26
C_L
10
48
49
34
22
27
35
20
34
27
35
40
34
48
18
18
48
46
24
46
16
32
33
38
32
28
33
14
32
44
44
C_L
26
12

FIG. 1



77
58
59
38
72
74
14
70
100, 104
32
108
33
110
32
100, 106
100,102
114
112
110
112
108
130
132
54
120
118
122
128
50
52
57
56
100
62
73
60
71
77

FIG. 2




FIG. 3



14
70
71
100, 104
72
112
73
100, 106
110
74
32
52
100, 102
112
114
116
110
124
128
126
132
130
115
136
50
4/9

FIG. 4



14
74
100, 106
110
73
100, 104
72
71
70
100, 102
112
32
126
124
114
108
130
50
52
128
115
132
116
113
111
134
122
118
120
136

FIG. 5



110
113
108
100, 102
112
132
113
120
118
126
122
130
124
114
116
111
124
128
134
111
126

FIG. 6



113
116
100, 102
108
122
110
113
120
118
114
132
130
126
115
124
122
118
120
126
124
112
111

FIG. 7



110
113
110, 104
126
108
122
116
120
113
124
118
116
114
115
134
111
115
111
112

FIG. 8



113
108
126
113
116
100, 104
132
132
124
115
130
130
114
122
116
128
112
118
111
111
134
115
110

FIG. 9



C
100
110
115
132
126
132
115
132
132
131
142
115
108
130
131
111
113
138
140
136
136
127
134
128
129
116

FIG. 10



100
110
115
115
142
115
108
111
113
126
138
136
136
140

FIG. 11



1200
MOUNT THE TOOLING ASSEMBLY TO ONE OR MORE ROTOR BLADES OF THE TURBOMACHINE VIA AN AXIAL MOUNTING PORTION OF THE TOOLING ASSEMBLY
1202
COMPRESS, VIA A COMPRESSOR BAR OF THE RADIAL COMPRESSION PORTION, ONE OR MORE T-FAIRINGS IN THE T-FAIRING RING
1204
ROTATE THE T-FAIRING RING CIRCUMFERENTIALLY WITHIN THE SLOT SUCH THAT NO T-FAIRING IN THE T-FAIRING RING IS DISPOSED ENTIRELY WITHIN A WINDOW OF THE SLOT
1206

FIG. 12