



G00002

ABSTRACT



Process for rendering sludges inert

162162

Process for rendering inert a sludge (1) comprising heavy metals and organic matter, according to which phosphoric acid (2) is added to the sludge and the latter is subjected to calcination (6). A hydraulic binder (9) is mixed with the product of the calcination (7) and mixed with water (8). The resulting mixture (11) is subjected to setting and curing.

Figure 1.