


┌

1/8

FIG. 1
Example 1 - MCM-56, 68 hrs @ 160°C




└

┐

2/8

FIG. 2
Example 2 - MCM-56, 68 hrs @ 160°C




┐

┐

3/8

FIG. 3
Example 3 - MCM-56, 40 hrs @ 160°C




┐

┐

4/8

FIG. 4
Example 4 - MCM-56, 68 hrs @ 160°C




└

┐

5/8


FIG. 5
Example 5 - MCM-56, 38 hrs @ 160°C



┐

┌

FIG. 6
Example 6 - MCM-56, 42 hrs @ 160°C




└

┌

7/8


FIG. 7
Example 7 - MCM-56, 32 hrs @ 160°C



└

┌

FIG. 8
Example 8 - MCM-49, 68 hrs @ 160°C



└