ABSTRACT

A method for reporting a measurement report is applied to a first terminal, and includes: receiving a radio resource control (RRC) message of a base station; determining a first threshold value and a second threshold value according to the RRC message; and determining to send the measurement report to the base station according to the first threshold value and a sidelink reference signal receiving power (SL-RSRP), or according to the second threshold value and a sidelink discovery reference signal receiving power (SD-RSRP).

FIG. 2