

FIG. 1A




FIG. 1B




FIG. 1C




FIG. 1D




FIG. 2




FIG. 3





FIG. 4A



(CROSS - SECTIONAL VIEW TAKEN ALONG X - X)

FIG. 4B




FIG. 5




FIG. 6





FIG. 7

(a)



(b)




FIG. 8




FIG. 9A




Fig. 1 is a cross-sectional view of a mechanical assembly. It features a base 51 with a vertical member 52 and a curved member 53. Dimensions include D1, D1', D2, S3, S4, S5, S6, and S7. Labels 52a, 52b, 52a1, 52a2, 52b1, 52b2, 55, 49, 46a, and 53 identify various parts and surfaces.

(CROSS - SECTIONAL VIEW TAKEN ALONG X - X)

FIG. 10




FIG. 11A




FIG. 11B




FIG. 11C




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16A




FIG. 16B




FIG. 17




FIG. 18A




FIG. 18B




FIG. 19A




FIG. 19B




FIG. 20A




FIG. 20B




FIG. 21




FIG. 22

